



STEELDAY 2024

10/18/24



DRIVING DIRECTIONS

Please Note the following Addresses
for the Morning and Afternoon portions of the event.

Morning Program - Project Showcase:

The High Auditorium at St Joseph's University
850 Greenfield Rd, Lancaster, PA 17601

(The Auditorium's entrance is at the rear of the Cooper Building, Door #16. Parking attendants will be available to direct you.)



Afternoon Program - BBQ and Tour:

High Steel Structures,
1911 Old Philadelphia Pike
Lancaster, PA 17602



Note: If you are **NOT** attending the technical session and are going straight to the plant at noon for the BBQ/Tour, please use the address 1911 Old Philadelphia Pike, Lancaster, PA 17602 for your GPS navigation. Enter off of Old Philadelphia Pike into the upper lot at the sign marked 1911 Plant One Human Resources.



STEELDAY PROGRAM

Project Showcase

*The High Auditorium at St. Joseph's University
850 Greenfield Rd, Lancaster, PA 17601 (Rear Entrance)*

8:00 AM - Continental Breakfast and Guest Check-in

9:30 AM - Program Begins

Welcome

Rich Truxel, VP of Sales, High Steel

Opening Remarks

Michael Carroll, Pennsylvania Secretary of Transportation

Project Presentations

Central Access Philadelphia (CAP)

Debbie Ferraro, P.E., Pennoni

Dave Warner, Vice President, Buckley & Co.

I-95 Over Cottman Avenue Emergency Bridge Replacement

Robert Buckley, President, Buckley & Co.

Din Abazi, P.E., District Executive, PennDOT

Harold Windisch, P.E., ACE, PennDOT

Archie Filshill, PH.D, CEO, Aero Aggregates of North America, LLC

High Steel Structures Open House

1911 Old Philadelphia Pike, Lancaster, PA 17602

Noon - 3:00 PM

BBQ Picnic, Shop Tours and Welding Demonstrations



SAFETY INFORMATION

Safety Information

Shop Tours and Virtual Welding Demos

Two hour guided walking tour of our fabrication facilities.

PPE will be provided, or you may bring your own.

Before arrival, please review these important safety and dress code guidelines:

High Steel Structures LLC holds the safety of all colleagues and visitors as a number one priority.

While in any work area, please follow the guidelines listed below:

- High Steel's Facilities and Property are tobacco free.
- Long pants and socks are required. No sleeveless shirts permitted.
- Hard-soled shoes or boots required. (No sneakers, high-heels, open toed shoes, or sandals.)
- Hard Hats, Safety Glasses, and Ear Plugs are required. PPE will be provided if you don't bring your own.
- Do not stare at weld or plasma arcs or flash.
- Stay in the designated walkways. Do not enter individual work areas unless authorized.
- When crane horns sound, stop, look and determine the crane path. Clear yourself of the crane path by moving to designated walkways along the walls. Never position yourself under or near a suspended load.
- Use personnel doors when entering or leaving the fabrication buildings.
- In the unlikely event of an evacuation, proceed in an orderly fashion to the visitor parking area.
- In the unlikely event of injury, immediately notify the Company Representative, Tour Guide, or Supervisor of the area. Ask for a First Aid evaluation.

Questions? Please contact Lisa Masters at LMasters@high.net

